



INSPECTION REPORT

REPORT # 60815171703
INVOICE # 60815171700

CUSTOMER ProMag RIG LOCATION Gray, La

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				ACC. REJ.	LENGTH	FULL LENGTH			
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC. REJ.	CONN. TYPE	BOX OD				BEV DIA.	CBORE DIA.	CBORE DEPTH
1.	MT-8150	4" X 8" Carbon steel plate fulllength bidirectional LPI of welds using water washable dye- (1) linear crack found rejected (#1 Linear crack found 1-1/4" from reference line 11/16" total length)														
2.																
3.																
4.																
5.																
6.																
7.																
8.																
9.																
10.																
11.																
12.																
13.																
14.																
15.																

INSPECTOR:

DATE: 8/15/17

LEVEL II

Rev 1b

SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5
 DSI OTHER

() Bodies F/L Bidirectional Wet Dry
 () Bodies F/L Transverse Wet Dry
 () Connections Comments 20 min. dwell time 10 min. developer time