



INSPECTION REPORT

REPORT # **60815171702**
 INVOICE # **60815171700**

CUSTOMER **ProMag** LOCATION **Gray, La** RIG _____

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS			BOX DIMENSIONS			CONN. TYPE	ACC. REJ.	TONG SPACE	PIN LTH	BEV DIA.	BOX OD	CONN. TYPE	REV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.	LENGTH	FULL LENGTH
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC. REJ.														
1.	MT-8146	4" X 8" Carbon steel plate fulllength bidirectional MPI of welds - (2) linear cracks found rejected (#1 Linear crack found 3/4" from reference line 7/8" total length & #2 linear crack found 2-3/4" from reference line 5/16" total length)																				
2.																						
3.																						
4.																						
5.																						
6.																						
7.																						
8.																						
9.																						
10.																						
11.																						
12.																						
13.																						
14.																						
15.																						

() Bodies F/L Bidirectional Wet Dry

() Bodies F/L Transverse Wet Dry

() Connections Comments _____

SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5 DSI OTHER _____

INSPECTOR: _____ DATE: 8/15/17 LEVEL II