



INSPECTION REPORT

CUSTOMER: **MAYO NDT**

RIG

LOCATION: **BROUSSARD**

REPORT #

70816170601

INVOICE #

70816170600

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				ACC. REL.	TONG SPACE	CBORE DEPTH	TONG SPACE	ACC. REL.	LENGTH	FULL LENGTH
			PIN OD	PIN ID	BEV DIA.	PIN LTH	CONN. TYPE	BOX OD	BEV DIA.	CBORE DIA.							
1.	MT-8145	CARBON STEEL 4"X8" TEST PLATE INSPECTED (1) CRACK FOUND 5/8 REFERENCE AND 7/16 LONG (REJECTED)															
2.																	
3.																	
4.																	
5.																	
6.																	
7.																	
8.																	
9.																	
10.																	
11.																	
12.																	
13.																	
14.																	
15.																	

() Bodies F/L Bidirectional Wet Dry

() Bodies F/L Transverse Wet Dry

() Connections Comments _____

SPECIFICATIONS: PRO-MAG SOP 100 200 300 400 500 600 800

DSI 3 to 5 DSI OTHER _____

DATE: **8/16/17**

INSPECTOR: **ACE MAYO**

LEVEL II