



INSPECTION REPORT

REPORT # 70320190801	INVOICE# 70320190800
-------------------------	-------------------------

CUSTOMER PRO-MAG	RIG	LOCATION BROUSSARD
---------------------	-----	-----------------------

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS							BOX DIMENSIONS							
			CONN. TYPE	PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC REJ.	CONN. TYPE	BOX OD	BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.	LENGTH
1.	MT-8145	TEST FIXER-INDICATION FOUND 1/2 INCH FROM FACE 1/2 LONG															
2.																	
3.																	
4.																	
5.																	
6.																	
7.																	
8.																	
9.																	
10.																	
11.																	
12.																	
13.																	
14.																	
15.																	

() Bodies F/L Bidirectional Wet Dry
 () Bodies F/L Transverse Wet Dry
 () Connections Comments _____

SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5
 DSI OTHER _____

INSPECTOR: *Acu Montoya* LEVEL II

DATE: 3/20/19