



# INSPECTION REPORT

CUSTOMER Pro Mag

RIG

LOCATION Houma, LA

REPORT #

40307190802

INVOICE#

40307190800

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				FULL LENGTH					
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC REJ.	CONN. TYPE	BOX OD		BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.
1.	VT-3783	4" x 8" Carbon Steel Test Block	LPI of weld using water washable visible die- One linear crack found 2-1/16" from reference point and it is 7/16" length													
2.																
3.																
4.																
5.																
6.																
7.																
8.																
9.																
10.																
11.																
12.																
13.																
14.																
15.																

( ) Bodies F/L Bidirectional  Wet  Dry  
( ) Bodies F/L Transverse  Wet  Dry  
( ) Connections Comments \_\_\_\_\_  
 DSI 3 to 5  DSI  OTHER

SPECIFICATIONS:  
PRO-MAG SOP  100  200  300  400  500  600  800  
 DATE: 3/7/19

INSPECTOR: Heath Plummer LEVEL II



# INSPECTION REPORT

REPORT #  
40307190802

INVOICE#  
40307190800

RIG LOCATION Houma, LA

CUSTOMER Pro Mag

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				FULL LENGTH							
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC REJ.	CONN. TYPE	BOX OD		BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.		
1.	VT-3783	4" x 8" Carbon Steel Test Block LPI of weld using water washable visible die- One linear crack found 2-1/16" from reference point and it is 7/16" length																
2.																		
3.																		
4.																		
5.																		
6.																		
7.																		
8.																		
9.																		
10.																		
11.																		
12.																		
13.																		
14.																		
15.																		

Bodies F/L Bidirectional     Wet     Dry  
 Bodies F/L Transverse     Wet     Dry  
 Connections    Comments \_\_\_\_\_  
 SPECIFICATIONS:  
 PRO-MAG SOP     100     200     300     400     500     600     800  
 DSI 3 to 5     DSI     OTHER \_\_\_\_\_  
 INSPECTOR: Heath Plummer    DATE: 3/7/19    LEVEL: II