



INSPECTION REPORT

REPORT #
40307190801

INVOICE #
40307190800

RIG _____
LOCATION Houma, LA

CUSTOMER Pro Mag

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				FULL LENGTH					
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC. REJ.	CONN. TYPE	BOX OD		BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.
1.	MT-8145	4" x 8" Carbon Steel Test Block MPI of weld- 1 linear cracks found, crack is a little off the weld 5/8" from reference point and 3/8" long														
2.																
3.																
4.																
5.																
6.																
7.																
8.																
9.																
10.																
11.																
12.																
13.																
14.																
15.																

(1) Bodies F/L Bidirectional Wet Dry
 () Bodies F/L Transverse Wet Dry
 () Connections Comments _____
 () DSI 3 to 5 DSI OTHER

SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5 DSI OTHER

INSPECTOR: Heath Kramer LEVEL II
 DATE: 3/7/19