



INSPECTION REPORT

REPORT # 40815171702
 INVOICE# 40815171700

CUSTOMER Pro Mag RIG LOCATION Houma, LA

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				FULL LENGTH							
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC. REL.	CONN. TYPE	BOX OD		BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REL.		
1.	8143	4" x 8" Carbon Steel Test Block MPI of weld- 2 linear cracks found, crack #1 is a little off the weld 2-15/16" from reference point and 1/2" long, crack #2 is right along the weld 1-1/2" from the reference point and 1/4" long																
2.																		
3.																		
4.																		
5.																		
6.																		
7.																		
8.																		
9.																		
10.																		
11.																		
12.																		
13.																		
14.																		
15.																		

Wet Dry
 Bodies F/L Bidirectional Wet Dry
 Bodies F/L Transverse Wet Dry
 Connections Comments _____
 SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5 DSI OTHER _____
 INSPECTOR: Keith Pramer DATE: 8/15/17 LEVEL II