



INSPECTION REPORT

REPORT #
60307190802

INVOICE #
60307190800

CUSTOMER ProMag RIG LOCATION Gray, La

NO.	SER. #	TYPE EQUIP.	PIN DIMENSIONS				BOX DIMENSIONS				FULL LENGTH									
			PIN OD	PIN ID	BEV DIA.	PIN LTH	TONG SPACE	ACC. REJ.	CONN. TYPE	BOX OD		BEV DIA.	CBORE DIA.	CBORE DEPTH	TONG SPACE	ACC. REJ.	LENGTH			
1.	MT-8143	4" X 8" Carbon steel plate fulllength bidirectional MPI of welds - (2) linear cracks found rejected (#1 Linear crack found 2-15/16" from reference line 9/16" total length & #2 linear crack found 1-1/2" from reference line 3/8" total length)																		
2.																				
3.																				
4.																				
5.																				
6.																				
7.																				
8.																				
9.																				
10.																				
11.																				
12.																				
13.																				
14.																				
15.																				

() Bodies F/L Bidirectional Wet Dry

() Bodies F/L Transverse Wet Dry

() Connections Comments _____

SPECIFICATIONS:
 PRO-MAG SOP 100 200 300 400 500 600 800
 DSI 3 to 5 DSI OTHER _____

Samir

INSPECTOR: _____ LEVEL II

DATE: 3/7/19