



Grade: 100 %

### Ultrasonic Inspection Level II Test Practical

Number of Points Deduct: 0

Print Name: Paul Bourg Date: 3/7/2019

Signature: *Paul Bourg*

Test Specimen: 8147

Level III Reviewer Signature: *Derrick N. Mayo* Cert#148577 Date: 3/7/2019

#### 10 Point Practical Checklist

	<u>Points Deducted</u> (Maximum 10)
1. Did the examinee exhibit knowledge and understanding of the method and equipment to be utilized in testing?	<u>0</u>
2. Did the examinee select the proper equipment to be used during the examination.	<u>0</u>
3. Did the examinee perform the proper calibration check of the equipment?	<u>0</u>
4. Did the examinee perform a proper set-up and/or prepare the specimen properly for testing?	<u>0</u>
5. Did the examinee use proper techniques during the examination sequence?	<u>0</u>
6. Did the examinee adhere to proper or common NDT procedural aspects during the examination?	<u>0</u>
7. Did the examinee exhibit any unsafe practices relative to the NDE method or equipment used during the examination? No	<u>0</u>
8. Did the examinee detect the known discontinuities in the test specimen?	<u>0</u>
9. Did the examinee properly evaluate the specific discontinuities found?	<u>0</u>
10. Did the examinee properly report the test parameters and results of evaluation?	<u>0</u>